15010 FM 2100, Suite 200 Crosby, Texas 77532 Telephone 281 328 3541 Fax 281 328 4687

97 OCT -7 PH 12: 15

La control of the second



R.L. Sloan, Sr. Manager Remediation

October 6, 1997

Mr. Ernest Franke, Project Manager USEPA - Superfund Compliance Section 1445 Ross Ave., 6H-ET Dallas, TX 75202

Re: French Monitoring Report

Dear Ernest:

Attached is the French site groundwater sampling report for the 3rd quarter, 1997.

There were no significant changes in groundwater gradients or in chemical composition. The chemical concentrations are generally on a declining trend. The dissolved oxygen content is generally low, which suggests that supplemental oxygen additions may expedite the natural attenuation process; this will be evaluated as part of the modeling update in December, 1997.

There is no current risk to the public health or the environment.

Please contact me if you have any questions or comments.

Sincerely,

R.L. Sloan

RS/ks

c: Amy Lange
John Glass
Dick Woodward
Jim Thomson
Emmanuel Ndame

Attachment



193188